

PRODUCT	2X02PC
---------	--------

Software 7.2.0.13

Release Date 27/06/22

- Added cursor movement to floor fields and fixed cursor movement on other fields
- 

Software 7.2.0.12

Release Date 13/06/22

- Added the facility to adjust calling time and lock command on 4212 with firmware 3.3.0 or higher.
- 

Software 7.2.0.11

Release Date 12/05/22

- Added the facility to enter proximity card numbers as well as site code and user code.
  - Improved individual block save and upload processes
- 

Software 7.2.0.7

Release Date 29/04/22

- Added Save block as feature to strip out a single block and save it as a new dat file.
- 

Software 7.2.0.6

Release Date 16/03/22

- Fixed bug with downloading from digital panel 2202 where floor and lift door data was lost.
- 

Software 7.2.0.5

Release Date 13/03/22

- Added support for 2216 R1 lift interface which has programmable relay times and allows multiple relays to be triggered.
- 

Software 7.2.0.4

Release Date 23/02/22

- Added ability to abort device search during start up.
  - Fixed bug with virtual Bluetooth ports causing program to hang during start up
  - Updated splash screen
-

Software 7.2.0.3

Release Date 20/12/21

- Added ability to choose which fobs to upload to a 4284X or 4384X intercom panel.
- 

Software 7.2.0.2

Release Date 04/06/21

- Added programming option for CST2310 VX2300 concierge
- 

Software 7.1.1.4

Release Date 16/03/21

- Added changes to the dat file loading function ready for the PC concierge
  - Added name field for 4284X & 4384X proximity users
- 

Software 7.1.1.3

Release Date 07/01/21

- Changed delay between bytes upload for 4284/4384 from 1.2mS to 3mS
- 

Software 7.1.1.2

Release Date 13/11/20

- Added changes to the dat file loading function ready for the PC concierge
- 

Software 7.1.1.1

Release Date 14/10/20

- Fixed bug when sorting apartment on 4212 (It didn't update the prox & codes to apartment pairing).
  - Change apt, code & prox forms behaviour with the mouse scroll wheel.
- 

Software 7.1.0.9

Release Date 28/02/20

- Fixed bug when changing to MAIN mode on 4384, it would revert to LOCAL.
- 

Software 7.1.0.8

Release Date 16/01/20

- Fixed small bug in automatic update checker
- 

Software 7.1.0.7

Release Date 06/01/20

- Added check for updates with redirect the download page if available
- 

Software 7.1.0.6

Release Date 11/09/19

- Fixed bug when downloading from a 4212 door panel. Downloading stopped at 24%. Cause – last update to include lift interfaces.
-